

Tree Impact Coordination Booklet

2020/2021 Interlachen Park Improvements



202 OAKWOOD ROAD 216 OAKWOOD ROAD



TREE SAVED - ASH TREATMENT

221 OAKWOOD ROAD



- ID #338
- SPECIES – ASH
- 34" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - ASH TREATMENT

221 OAKWOOD ROAD



- ID #339
- SPECIES – ASH
- 3.5" DIAMETER
- REMOVAL DUE TO SPECIES

221 OAKWOOD ROAD



- ID #337
- SPECIES – MAPLE
- 9" DIAMETER
- REMOVAL DUE TO POOR HEALTH

241 OAKWOOD ROAD




- ID #345
- SPECIES – ASH
- 15.5" DIAMETER
- REMOVAL DUE TO SPECIES

6 INTERLACHEN ROAD




- ID #92
- SPECIES – HONEYLOCUST
- 26" DIAMETER
- REMOVAL DUE TO POOR HEALTH

6 INTERLACHEN ROAD



TREE SAVED - TRENCHLESS WATER SERVICE REPLACEMENT

11 INTERLACHEN ROAD



15 INTERLACHEN ROAD



- ID #77
- SPECIES – MAPLE
- 18.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

101 INTERLACHEN ROAD



- ID #297
- SPECIES – ELM
- 39" DIAMETER
- REMOVAL DUE TO POOR HEALTH

133 INTERLACHEN ROAD 148 INTERLACHEN ROAD



- ID #303
- SPECIES – MAPLE
- 12.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH



- ID #289
- SPECIES – MAPLE
- 44" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

200 INTERLACHEN ROAD



- ID #331
- SPECIES – ASH
- 21" DIAMETER
- REMOVAL DUE TO SPECIES

209 INTERLACHEN ROAD



- ID #313
- SPECIES – MAPLE
- 14" DIAMETER
- REMOVAL DUE TO POOR HEALTH

220 INTERLACHEN ROAD 225 INTERLACHEN ROAD



233 INTERLACHEN ROAD



- ID #315
- SPECIES – MAPLE
- 19" DIAMETER
- REMOVAL DUE TO POOR HEALTH

3 MAPLE HILL ROAD



TREE SAVED - TRENCHLESS SEWER REPLACEMENT

14 MAPLE HILL ROAD



14 MAPLE HILL ROAD



TREE SAVED - NO LONGER CONFLICT

14 MAPLE HILL ROAD



100 MAPLE HILL ROAD



- ID #374
- SPECIES – MAPLE
- 1" DIAMETER
- REMOVAL DUE TO POOR HEALTH

100 MAPLE HILL ROAD



- ID #375
- SPECIES – ELM
- 37" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

101 MAPLE HILL ROAD



- ID #378
- SPECIES – SPRUCE
- 10" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

145 MAPLE HILL ROAD




- ID #382
- SPECIES – MAPLE
- 10.5" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

153 MAPLE HILL ROAD



200 MAPLE HILL ROAD



201 MAPLE HILL ROAD



218 MAPLE HILL ROAD



240 MAPLE HILL ROAD



245 MAPLE HILL ROAD




1 HOMEDALE ROAD



TREE SAVED - TRENCHLESS WATER SERVICE REPLACEMENT

5 HOMEDALE ROAD



6 HOMEDALE ROAD



9 HOMEDALE ROAD



10 HOMEDALE ROAD



14 HOMEDALE ROAD



TREE SAVED - TRENCHLESS WATER REPLACEMENT


25 HOMEDALE ROAD



100 HOMEDALE ROAD




101 HOMEDALE ROAD



- ID #102
- SPECIES – ASH
- 27" DIAMETER
- REMOVAL DUE TO SPECIES

129 HOMEDALE ROAD




- ID #401
- SPECIES – ASH
- 29" DIAMETER
- REMOVAL DUE TO SPECIES

132 HOMEDALE ROAD



- ID #393
- SPECIES – MAPLE
- 31" DIAMETER
- REMOVAL DUE TO POOR HEALTH

137 HOMEDALE ROAD



- ID #403
- SPECIES – ASH
- 9" DIAMETER
- REMOVAL DUE TO SPECIES

144 HOMEDALE ROAD



- ID #391
- SPECIES – ASH
- 13" DIAMETER
- REMOVAL DUE TO SPECIES

154 HOMEDALE ROAD



- ID #390
- SPECIES – CRABAPPLE
- 7" DIAMETER
- REMOVAL DUE TO WATER SERVICE CONFLICT

154 HOMEDALE ROAD



4 HAWTHORNE ROAD



- ID #34
- SPECIES – MAPLE
- 2.5" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

7 HAWTHORNE ROAD



- ID #27
- SPECIES – MAPLE
- 11" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

11 HAWTHORNE ROAD



14 HAWTHORNE ROAD

