


Tree Impact Coordination Booklet 2020/2021 Interlachen Park Improvements



19 HAWTHORNE ROAD



- ID #21
- SPECIES – ASH
- 17.5" DIAMETER
- REMOVAL DUE TO SPECIES

98 HAWTHORNE ROAD



- ID #40
- SPECIES – ASH
- 16" DIAMETER
- REMOVAL DUE TO SPECIES

100 HAWTHORNE ROAD



- ID #421
- SPECIES – ASH
- 8" DIAMETER
- REMOVAL DUE TO SPECIES

101 HAWTHORNE ROAD



- ID #106
- SPECIES – MAPLE
- 16.5" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

112 HAWTHORNE ROAD



- ID #419
- SPECIES – ELM
- 24" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

TREE SAVED - ASH TREATMENT


117 HAWTHORNE ROAD



- ID #43
- SPECIES – ASH
- 8.5" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - TRENCHLESS WATER REPLACEMENT

117 HAWTHORNE ROAD



- ID #430
- SPECIES - ELM
- 32" DIAMETER
- REMOVAL DUE TO WATER SERVICE CONFLICT

117 HAWTHORNE ROAD



- ID #429
- SPECIES - ASH
- 6.5" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - ASH TREATMENT

117 HAWTHORNE ROAD



- ID #473
- SPECIES – ASH
- 11.5" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - ASH TREATMENT

117 HAWTHORNE ROAD



- ID #473
- SPECIES – ASH
- 11" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - TRENCHLESS WATER REPLACEMENT

125 HAWTHORNE ROAD



128 HAWTHORNE ROAD



133 HAWTHORNE ROAD



- ID #436
- SPECIES – ELM
- 32" DIAMETER
- REMOVAL DUE TO STREET CONFLICT


TREE SAVED - TRENCHLESS WATER & SEWER REPLACEMENT

136 HAWTHORNE ROAD



- ID #436
- SPECIES – MAPLE
- 36" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICT

144 HAWTHORNE ROAD



- ID #411
- SPECIES – ELM
- 36.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

TREE SAVED - TRENCHLESS WATER REPLACEMENT

214 HAWTHORNE ROAD



- ID #48
- SPECIES – MAPLE
- 8" DIAMETER
- REMOVAL DUE TO WATER SERVICE CONFLICT

TREE SAVED - TRENCHLESS WATER &
SEWER REPLACEMENT

215 HAWTHORNE ROAD



- ID #474
- SPECIES – MAPLE
- 17" DIAMETER
- REMOVAL DUE TO
SANITARY & WATER
SERVICE CONFLICTS

228 HAWTHORNE ROAD




- ID #486
- SPECIES – MAPLE
- 24.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

228 HAWTHORNE ROAD



- ID #485
- SPECIES – ASH
- 15" DIAMETER
- REMOVAL DUE TO SPECIES

240 HAWTHORNE ROAD



- ID #484
- SPECIES – ASH
- 29" DIAMETER
- REMOVAL DUE TO SPECIES

98 MEADOWBROOK ROAD



- ID #6
- SPECIES – MAPLE
- 28" DIAMETER
- REMOVAL DUE TO POOR HEALTH

98 MEADOWBROOK ROAD



- ID #7
- SPECIES – MAPLE
- 20.5" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

98 MEADOWBROOK ROAD



- ID #8
- SPECIES – MAPLE
- 20.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

122 MEADOWBROOK ROAD



- ID #454
- SPECIES – MAPLE
- 14.5" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

TREE SAVED - TRENCHLESS WATER REPLACEMENT

114 MEADOWBROOK ROAD



- ID #45
- SPECIES – HONEY LOCUST
- 22" DIAMETER
- REMOVAL DUE TO WATER SERVICE CONFLICT

140 MEADOWBROOK ROAD



- ID #454
- SPECIES – SPRUCE
- 12" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

TREE SAVED - NO LONGER CONFLICT

201 MEADOWBROOK ROAD



- ID #46
- SPECIES – OAK
- 30.5" DIAMETER
- REMOVAL DUE TO TRAIL CONFLICT

TREE SAVED - NO LONGER CONFLICT

201 MEADOWBROOK ROAD




- ID #N/A
- SPECIES – N/A
- N/A DIAMETER
- REMOVAL DUE TO TRAIL CONFLICT

200 MEADOWBROOK ROAD




- ID #468
- SPECIES – MAPLE
- 17" DIAMETER
- REMOVAL DUE TO POOR HEALTH

212 MEADOWBROOK ROAD




- ID #463
- SPECIES – ASH
- 10" DIAMETER
- REMOVAL DUE TO SPECIES

216 MEADOWBROOK ROAD



- ID #461
- SPECIES – ASH
- 9.5" DIAMETER
- REMOVAL DUE TO SPECIES

216 MEADOWBROOK ROAD



- ID #459
- SPECIES – HACKBERRY
- 15.5" DIAMETER
- REMOVAL DUE TO STREET CONFLICT


TREE SAVED - NO LONGER CONFLICT SANITARY SERVICE - VERIFIED WITH TV INSPECTION

216 MEADOWBROOK ROAD



- ID #453
- SPECIES – MAPLE
- 18" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

248 MEADOWBROOK ROAD




- ID #447
- SPECIES – SPRUCE
- 8.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

248 MEADOWBROOK ROAD



- ID #445
- SPECIES – ASH
- 5" DIAMETER
- REMOVAL DUE TO SPECIES

248 MEADOWBROOK ROAD



- ID #448
- SPECIES – ASH
- 10" DIAMETER
- REMOVAL DUE TO SPECIES

TREE SAVED - NO LONGER CONFLICT SANITARY SERVICE - VERIFIED WITH TV INSPECTION

1310 PRESTON LANE



- ID #131
- SPECIES – HAWK BERRY
- 12.5" DIAMETER
- REMOVAL DUE TO SANITARY SERVICE CONFLICT

1319 PRESTON LANE



- ID #143
- SPECIES – ASH
- 16" DIAMETER
- REMOVAL DUE TO SPECIES

1401 PRESTON LANE




- ID #139
- SPECIES – HACKBERRY
- 14.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

1409 PRESTON LANE




- ID #138
- SPECIES – ASH
- 22.5" DIAMETER
- REMOVAL DUE TO SPECIES

1410 PRESTON LANE



- ID #132
- SPECIES – ASH
- 25" DIAMETER
- REMOVAL DUE TO SPECIES

1615 PRESTON LANE



- ID #55
- SPECIES – ASH
- 24" DIAMETER
- REMOVAL DUE TO SPECIES

1509 PRESTON LANE



- ID #137
- SPECIES – HONEYLOCUST
- 1.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

1321 BOYCE STREET



- ID #121
- SPECIES – HONEYLOCUST
- 9" DIAMETER
- REMOVAL DUE TO SANITARY & WATER SERVICE CONFLICTS

1327 BOYCE STREET



- ID #120
- SPECIES – ASH
- 33" DIAMETER
- REMOVAL DUE TO SPECIES

1405 BOYCE STREET



- ID #119
- SPECIES – MAPLE
- 18.5" DIAMETER
- REMOVAL DUE TO STREET CONFLICT

1409 BOYCE STREET



- ID #118
- SPECIES – LINDEN
- 11.5" DIAMETER
- REMOVAL DUE TO POOR HEALTH

1417 BOYCE STREET



121 BLAKE ROAD S

