

Crash Severity/Crash Year											
Crash Severity	Total	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
K - Fatal	0	0	0	0	0	0	0	0	0	0	0
A - Serious Injury	1	0	0	0	0	0	1	0	0	0	0
B - Minor Injury	1	0	0	0	0	0	0	0	1	0	0
C - Possible Injury	7	0	0	0	0	0	2	0	3	1	1
N - Prop Dmg Only	54	0	0	0	0	0	13	9	12	10	10
Total	63	0	0	0	0	0	16	9	16	11	11

Crash Severity/Number of Vehicles						
Crash Severity	Total	0	1	2	3+	
K - Fatal	0	0	0	0	0	
A - Serious Injury	1	0	0	1	0	
B - Minor Injury	1	0	1	0	0	
C - Possible Injury	7	0	3	3	1	
N - Prop Dmg Only	54	0	44	8	2	
Total	63	0	48	12	3	

Basic Type Summary	Total	%
Pedestrian	0	0.0
Bike	0	0.0
Single Vehicle Run Off Road	42	66.7
Single Vehicle Other	6	9.5
Sideswipe Same Direction	4	6.3
Sideswipe Opposing	0	0.0
Rear End	9	14.3
Head On	0	0.0
Left Turn	0	0.0
Angle	0	0.0
Other	2	3.2
Total	63	100.0

First Harmful Event Summary	Total	%
Pedestrian	0	0.0
Bicyclist	0	0.0
Motor Vehicle In Transport	15	23.8
Parked Motor Vehicle	0	0.0
Train	0	0.0
Deer/Animal	3	4.8
Other - Non Fixed Object	1	1.6
Collision Fixed Object	40	63.5
Non-Collision Harmful Events	3	4.8
Other/Unknown	1	1.6
Total	63	100.0

Relationship to Intersection Summary	Total	%
Not at Intersection/Interchange	53	84.1
Four-Way Intersection	0	0.0
T or Y Intersection	0	0.0
Five-Way Intersection or More	0	0.0
Roundabout	0	0.0
Intersection Related	0	0.0
Driveway Access Related	0	0.0
At School Crossing	0	0.0
Railway Grade Crossing	0	0.0
Shared Use Path or Trail	0	0.0
Interchange or Ramp	9	14.3
Crossover Related	1	1.6
Acceleration/Deceleration Lane	0	0.0
Other/Unknown	0	0.0
Total	63	100.0

Weather 1 Summary	Total	%
Clear	36	57.1
Cloudy	6	9.5
Rain	3	4.8
Snow	10	15.9
Sleet, Hail (Freezing Rain/Drizzle)	2	3.2
Fog/Smog/Smoke	0	0.0
Blowing Sand/Soil/Dirt/Snow	6	9.5
Severe Crosswinds	0	0.0
Other/Unknown	0	0.0
Total	63	100.0

Light Condition Summary	Total	%
Daylight	37	58.7
Sunrise	2	3.2
Sunset	1	1.6
Dark (Str Lights On)	12	19.0
Dark (Str Lights Off)	2	3.2
Dark (No Str Lights)	9	14.3
Dark (Unknown Light)	0	0.0
Other/Unknown	0	0.0
Total	63	100.0



From To	00:00 01:59	02:00 03:59	04:00 05:59	06:00 07:59	08:00 09:59	10:00 11:59	12:00 13:59	14:00 15:59	16:00 17:59	18:00 19:59	20:00 21:59	22:00 23:59	Total	%
SUN	1	0	1	1	0	3	1	0	3	0	0	0	10	15.9
MON	0	0	1	2	2	0	2	1	2	1	0	0	11	17.5
TUE	0	0	2	3	2	0	0	2	0	0	0	1	10	15.9
WED	0	0	1	1	2	2	0	0	1	0	1	0	8	12.7
THU	1	0	1	1	0	0	0	0	1	1	0	0	5	7.9
FRI	0	0	0	0	2	1	0	2	3	1	2	1	12	19.0
SAT	0	0	1	0	1	2	1	0	1	1	0	0	7	11.1
Total	2	0	7	8	9	8	4	5	11	4	3	2	63	100.0
%	3.2	0.0	11.1	12.7	14.3	12.7	6.3	7.9	17.5	6.3	4.8	3.2	100.0	100.0

Driver & N	Driver & Non-Motorist Age/Gender Summary					
Age	М	F	NR	No Value	Total	%
<14	0	0	0	0	0	0.0
14	0	0	0	0	0	0.0
15	0	0	0	0	0	0.0
16	0	0	0	0	0	0.0
17	1	0	0	0	1	1.2
18	4	0	0	0	4	4.9
19	2	3	0	0	5	6.2
20	2	1	0	0	3	3.7
21-24	9	6	0	0	15	18.5
25-29	5	2	0	0	7	8.6
30-34	5	1	0	0	6	7.4
35-39	10	1	0	0	11	13.6
40-44	4	1	0	0	5	6.2
45-49	1	1	0	0	2	2.5
50-54	1	3	0	0	4	4.9
55-59	3	0	0	0	3	3.7
60-64	4	0	0	0	4	4.9
65-69	1	2	0	0	3	3.7
70-74	2	1	0	0	3	3.7
75-79	2	1	0	0	3	3.7
80-84	1	0	0	0	1	1.2
85-89	0	0	0	0	0	0.0
90-94	0	0	0	0	0	0.0
95+	0	0	0	0	0	0.0
No Value	0	0	0	1	1	1.2
Total	57	23	0	1	81	100.0
%	70.4	28.4	0.0	1.2	100.0	100.0

Month Summary	Total	%
January	15	23.8
February	7	11.1
March	2	3.2
April	7	11.1
May	0	0.0
June	3	4.8
July	4	6.3
August	4	6.3
September	2	3.2
October	8	12.7
November	7	11.1
December	4	6.3
Total	63	100.0

Physical Condition Summary	Total	%
Apparently Normal (Including No Drugs/Alcohol)	71	88.8
Physical Disability (Short Term or Long Term)	1	1.2
Medical Issue (III, Sick or Fainted)	0	0.0
Emotional (Depression, Angry, Disturbed, etc.)	0	0.0
Asleep or Fatigued	3	3.8
Has Been Drinking Alcohol	4	5.0
Has Been Taking Illicit Drugs	1	1.2
Has Been Taking Medications	0	0.0
Other/Unknown	0	0.0
Not Applicable	0	0.0
Total	80	100.0

Sel	ection	Filt	er
-----	--------	------	----

WORK AREA: County('659485') - FILTER: Year('2019','2020','2021','2022','2023'), Relationship to Intersection('2','25','26','27','28','29') - SPATIAL FILTER APPLIED

Analyst:	Notes:
Bryan Nemeth	



Crash Severity/Crash Year											
Crash Severity	Total	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
K - Fatal	0	0	0	0	0	0	0	0	0	0	0
A - Serious Injury	0	0	0	0	0	0	0	0	0	0	0
B - Minor Injury	1	0	0	0	0	0	1	0	0	0	0
C - Possible Injury	1	0	0	0	0	0	0	0	0	1	0
N - Prop Dmg Only	4	0	0	0	0	0	1	0	1	1	1
Total	6	0	0	0	0	0	2	0	1	2	1

Crash Severity/Number of Vehicles									
Crash Severity	Total	0	1	2	3+				
K - Fatal	0	0	0	0	0				
A - Serious Injury	0	0	0	0	0				
B - Minor Injury	1	0	1	0	0				
C - Possible Injury	1	0	1	0	0				
N - Prop Dmg Only	4	0	4	0	0				
Total	6	0	6	0	0				

Basic Type Summary	Total	%
Pedestrian	0	0.0
Bike	0	0.0
Single Vehicle Run Off Road	4	66.7
Single Vehicle Other	2	33.3
Sideswipe Same Direction	0	0.0
Sideswipe Opposing	0	0.0
Rear End	0	0.0
Head On	0	0.0
Left Turn	0	0.0
Angle	0	0.0
Other	0	0.0
Total	6	100.0

First Harmful Event Summary	Total	%
Pedestrian	0	0.0
Bicyclist	0	0.0
Motor Vehicle In Transport	0	0.0
Parked Motor Vehicle	0	0.0
Train	0	0.0
Deer/Animal	2	33.3
Other - Non Fixed Object	0	0.0
Collision Fixed Object	2	33.3
Non-Collision Harmful Events	2	33.3
Other/Unknown	0	0.0
Total	6	100.0

Relationship to Intersection Summary	Total	%
Not at Intersection/Interchange	6	100.0
Four-Way Intersection	0	0.0
T or Y Intersection	0	0.0
Five-Way Intersection or More	0	0.0
Roundabout	0	0.0
Intersection Related	0	0.0
Driveway Access Related	0	0.0
At School Crossing	0	0.0
Railway Grade Crossing	0	0.0
Shared Use Path or Trail	0	0.0
Interchange or Ramp	0	0.0
Crossover Related	0	0.0
Acceleration/Deceleration Lane	0	0.0
Other/Unknown	0	0.0
Total	6	100.0

Weather 1 Summary	Total	%
Clear	3	50.0
Cloudy	0	0.0
Rain	0	0.0
Snow	1	16.7
Sleet, Hail (Freezing Rain/Drizzle)	2	33.3
Fog/Smog/Smoke	0	0.0
Blowing Sand/Soil/Dirt/Snow	0	0.0
Severe Crosswinds	0	0.0
Other/Unknown	0	0.0
Total	6	100.0

Light Condition Summary	Total	%
Daylight	2	33.3
Sunrise	0	0.0
Sunset	0	0.0
Dark (Str Lights On)	0	0.0
Dark (Str Lights Off)	0	0.0
Dark (No Str Lights)	4	66.7
Dark (Unknown Light)	0	0.0
Other/Unknown	0	0.0
Total	6	100.0



Time of Da	y/Day of	Week												
From To	00:00 01:59	02:00 03:59	04:00 05:59	06:00 07:59	08:00 09:59	10:00 11:59	12:00 13:59	14:00 15:59	16:00 17:59	18:00 19:59	20:00 21:59	22:00 23:59	Total	%
SUN	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0
MON	0	0	0	0	0	0	0	0	1	0	0	0	1	16.7
TUE	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0
WED	0	0	1	1	0	0	0	0	0	0	0	0	2	33.3
THU	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0
FRI	0	0	0	1	0	0	0	0	0	0	0	0	1	16.7
SAT	0	0	1	0	0	0	0	0	0	1	0	0	2	33.3
Total	0	0	2	2	0	0	0	0	1	1	0	0	6	100.0
%	0.0	0.0	33.3	33.3	0.0	0.0	0.0	0.0	16.7	16.7	0.0	0.0	100.0	100.0

L						
Driver & N	on-Motori	st Age/G	ender S	ummary		
Age	М	F	NR	No Value	Total	%
<14	0	0	0	0	0	0.0
14	0	0	0	0	0	0.0
15	0	0	0	0	0	0.0
16	0	0	0	0	0	0.0
17	0	0	0	0	0	0.0
18	0	0	0	0	0	0.0
19	0	0	0	0	0	0.0
20	0	0	0	0	0	0.0
21-24	1	0	0	0	1	16.7
25-29	2	0	0	0	2	33.3
30-34	1	0	0	0	1	16.7
35-39	0	0	0	0	0	0.0
40-44	1	0	0	0	1	16.7
45-49	0	0	0	0	0	0.0
50-54	0	0	0	0	0	0.0
55-59	0	0	0	0	0	0.0
60-64	0	0	0	0	0	0.0
65-69	0	0	0	0	0	0.0
70-74	0	0	0	0	0	0.0
75-79	0	0	0	0	0	0.0
80-84	0	0	0	0	0	0.0
85-89	0	0	0	0	0	0.0
90-94	0	0	0	0	0	0.0
95+	0	0	0	0	0	0.0
No Value	0	0	0	1	1	16.7
Total	5	0	0	1	6	100.0
%	83.3	0.0	0.0	16.7	100.0	100.0

Month Summary	Total	%
January	1	16.7
February	1	16.7
March	2	33.3
April	0	0.0
Мау	0	0.0
June	0	0.0
July	0	0.0
August	1	16.7
September	0	0.0
October	0	0.0
November	0	0.0
December	1	16.7
Total	6	100.0

Physical Condition Summary	Total	%
Apparently Normal (Including No Drugs/Alcohol)	3	60.0
Physical Disability (Short Term or Long Term)	0	0.0
Medical Issue (III, Sick or Fainted)	0	0.0
Emotional (Depression, Angry, Disturbed, etc.)	0	0.0
Asleep or Fatigued	0	0.0
Has Been Drinking Alcohol	0	0.0
Has Been Taking Illicit Drugs	0	0.0
Has Been Taking Medications	0	0.0
Other/Unknown	2	40.0
Not Applicable	0	0.0
Total	5	100.0

Sel	ection	Filt	er
-----	--------	------	----

WORK AREA: County('659485') - FILTER: Year('2019','2020','2021','2022','2023'), Relationship to Intersection('2','25','26','27','28','29') - SPATIAL FILTER APPLIED

Analyst:	Notes:
Bryan Nemeth	



Crash Detail Report - Short Form CSAH 28 Segment 5 Year

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUN	TY	С	YTI	
01065258	04-CSAH	0028	0.969	9	FOREST PRAIRIE RD 0400006594850028-I 40-L			40-Le	I0-Le Sueur NC		I TO	IN A CITY		
INTERSECT WITH		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UT	гм х	UTM Y	/	WORK ZONE TYPE	
			1	0	12/14/22	05:45	Wed	44.482409	-93.88378	6 42	29720.4	4925834	1.1	NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	,	FIRST	HARMFU	JL.			LIG	HT CONDI	TION	W	EATHER PRIMARY
Single Vehicle	Other	C - Poss	ble Inju	ry	Deer					Da	rk (No Str	Lights)	S	leet, Hail (Freezing Ra

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Eastbound			
Maneuver	Swerved or Attempt to Avoid			
Age/Sex	27 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			


OFFICER SKETCH

NARRATIVE

ON 12/14/2022 AT APPROXIMATELY 0548 HOURS, I, OFFICER SAENZ # 307 RESPONDED TO FOREST PRAIRIE ROAD NEAR BIMEDA FOR A SINGLE VEHICLE CRASH. THE CRASH OCCURRED EARLY IN THE MORNING, THE AREA THE CRASHED OCCURRED THERE WERE NO STREET LIGHTING, AND IT WAS DARK OUTSIDE. THERE WAS ALSO FREEZING RAIN, CAUSING THE ROADWAY TO BE SLICK. WHEN I ARRIVED ON SCENE THE DRIVER WAS STANDING OUTSIDE HIS TRUCK. THE DRIVER WAS IDENTIFIED BY HIS IMMIGRATION CARD AS TOMAS RIGOBERTO BRITO MARCOS(DOB:06/28/1995). MARCOS STATED HE WAS DRIVING TO WORK WHEN A DEER GOT ON THE ROADWAY. MARCOS WAS TRAVELING EAST UPHILL ON FOREST PRAIRIE ROAD NEAR BIMEDA. MARCOS STRUCK THE DEER AND PRESSED ON HIS BREAKS, HOWEVER DUE TO THE SLICKNESS OF THE ROADWAY HIS TRUCK SLID INTO THE DITCH. THE MOMENTUM OF THE VEHICLE AND SUDDEN STOP OF HITTING THE DITCH CAUSED

INCIDENT ID	NCIDENT ID ROUTE SYS ROUTE NUM MEASURE		SURE	ROUTE NAME			ROUTE ID CO		COU	COUNTY		CITY		
00697671	04-CSAH	0028	1.342	342 FOREST PRAIRIE RD 0400006594850			l850028-I	40-Le Sueur Le			Le S	Sueur		
INTERSECT WITH		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG		UTM X	UTM Y		WORK ZONE TYPE	
			1	0	03/13/19	06:00	Wed	44.486256	-93.87865	3	430133.2	492625	7.0	NOT APPLICABLE
BASIC TYPE CRASH SEVERITY			FIRST HARMFUL				L	LIGHT CONDITION WEATHER PRIMAR		WEATHER PRIMARY				
Single Vehicle	single Vehicle Run Off Road N - Prop Damage Only		Overt	Overturn/Rollover					Dark (No Str Lights)			Sleet, Hail (Freezing Ra		

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport **Unit Type** Vehicle Type Sport Utility Vehicle **Direction of Travel** Northbound Maneuver Moving Forward Age/Sex **Physical Cond Apparently Normal Contributing Factor 1** No Clear Contributing Action



NARRATIVE


DRIVER OF UNIT 1 WAS NORTHBOUND ON FOREST PRAIRIE RD AND DROVE OVER BLACK ICE CAUSING THE DRIVER OF UNIT 1 TO LOOSE CONTROL AND OVER TURN. DRIVER OF UNIT 1 WAS NOT SPEEDING AND WAS UNABLE TO CONTROL THE OUT COME OF THIS CRASH.



Crash Detail Report - Short Form CSAH 28 Segment 5 Year

INCIDENT ID	ROUTE SYS	ROUTE NUM	I MEAS	SURE	ROUTE NA	AME		ROUTE ID		COUNTY		CITY	
00683631	04-CSAH	0028	1.38	2	FOREST	PRAIRI	E RD	0400006594	850028-I	40-Le Sueur		Le S	Sueur
INTERSECT WI	TĤ		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE
			1	0	02/04/19	16:20	Mon	44.486560	-93.87798	430187.0	492629	90.3	NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	<i>'</i>	FIRST	HARMFU	JL			LIGHT COND	ITION	,	WEATHER PRIMARY
Single Vehicle	ingle Vehicle Run Off Road B - Minor Injury			Overt	Overturn/Rollover				Davlight			Clear	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	24 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			
Age/Sex Physical Cond	24 M Apparently Normal			




NARRATIVE

VEHICLE ONE WAS TRAVELING NORTH ON FORREST PRAIRIE ROAD. HE THEN HIT AN ICY SPOT AND CROSSED OVER THE CENTER LINE. HE THEN CORRECTED BACK INTO HIS LANE AND HIT ICE AND WENT STRAIGHT INTO A RAVINE. THE VEHICLE THEN ROLLED MULTIPLE TIMES LANDED ON ITS ROOF. IT WAS APPROXIMATELY 50-60 FOOT DROP TO THE BOTTOM OF THE RAVINE. THE DRIVER OF THE VEHICLE WAS TRANSPORTED VIA PRIVATE VEHICLE TO THE HOSPITAL AND HAD MINOR INJURIES (BUMPS AND BRUISING). AFFORDABLE TOWING CAME THE FOLLOWING DAY AND REMOVED THE VEHICLE FROM THE RAVINE. THERE WAS HEAVY DISABLING DAMAGE TO THE VEHICLE.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY	CI	TY
00874565	04-CSAH	0028	8 1.442		FOREST PRAIRIE RD		0400006594850028-1 40		40-Le Sueur	Le	Sueur	
INTERSECT WITH #		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
			1	0	01/15/21	07:25	Fri	44.486828	-93.87681	2 430280.3	4926319.	1 NOT APPLICABLE
BASIC TYPE	BASIC TYPE CRASH SEVERITY		,	FIRS1	HARMFU	L			LIGHT COND	TION	WEATHER PRIMARY	
Single Vehicle	Run Off Road	N - Prop Damage Only			Ditch	Ditch					Lights)	Snow

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Northbound			
Maneuver	Unknown			
Age/Sex				
Physical Cond				
Contributing Factor 1				



NAPPATIVE


ON 1/15/2021 AT 0725 HOURS I, CPT. AARON THIEKE, WAS DISPATCHED TO A VEHICLE OFF THE ROADWAY ON THE FOREST PRIARIE HILL. THE REPORTING PARTY STATED ALL LIGHTS WERE OFF AND NO ONE WAS AROUND THE VEHICLE. DEPUTY TODD LAU HAD BEEN DISPATCHED TO A CALL OF PEOPLE BLOCKING THE TRAFFIC LANE WHILE ATTEMPTING TO REMOVE A VEHICLE FROM THE DITCH IN THIS SAME AREA. UPON MY ARRIVAL I OBSERVED A TOW STRAP ATTACHED TO THE VEHICLE AND MANY TIRE TRACKS IN THE AREA INDICATING SEVERAL ATTEMPTS HAD BEEN MADE TO REMOVE THIS VEHICLE FROM THE STEEP DITCH EMBANKMENT. THE VEHICLE WAS A FORD EXPLORER WITH MN LIC 522TVK REGISTERED TO ROBERT MENDOZAMARINES OUT OF ARLINGTON. THERE WAS NO ONE AROUND THE VEHICLE. IT WAS DETERMINED THIS VEHICLE HAD BEEN THE SAME VEHICLE DEPUTY LAU WAS DISPATCHED TOO. THE VEHICLE WAS ONLY ABOUT 6 FEET OFF THE TRAFFIC LANE ON A SHARP CORNER



Crash Detail Report - Short Form CSAH 28 Segment 5 Year

INCIDENT ID F	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	ME		ROUTE ID		COUNTY	CIT	Υ
01041080	04-CSAH	0028	1.44	3	FOREST PRAIRIE RD 0400006594850028-I		850028-I	40-Le Sueur	Le	Sueur		
INTERSECT WITH # VEH			# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
			1	0	08/20/22	19:30	Sat	44.486829	-93.87680	5 430280.8	4926319.2	NOT APPLICABLE
BASIC TYPE CRASH SEVERITY				FIRST	FIRST HARMFUL					TION	WEATHER PRIMARY	
Single Vehicle R	ingle Vehicle Run Off Road N - Prop Damage Only			Ditch					Daylight		Clear	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Passenger Car			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	26 M			
Physical Cond	Unknown			
Contributing Factor 1	Ran Off Road			



NARRATIVE

AT APPROXIMATELY 0815 HOURS ON AUGUST 21, 2022 I, OFFICER DANIEL REICH, WAS DISPATCHED TO FOREST PRAIRIE RD SOUTH OF CAMBRIA FOR A MOTOR VEHICLE ACCIDENT. DISPATCH REPORTED A PASSERBY NOTICED THE VEHICLE IN A RAVINE AND SHORTLY AFTER SOME PEOPLE SHOWED UP. I RESPONDED TO THE LOCATION. I ARRIVED AND NOTICED SIX HISPANIC MALES. THE CALLER HAD SINCE LEFT THE AREA. I USED LANGUAGE LINE TO SPEAK WITH THE MALES. ONE MALE WAS IDENTIFIED AS JAIRO ANTONIO LUNO RIZO (DOB 06/07/1996). JAIRO DID NOT HAVE ANY IDENTIFICATION FROM ANY STATE AND TOLD ME IMMIGRATION HAD TAKEN IT FROM HIM. JAIRO PROVIDED ME A BLUEBONNET DETENTION CENTER ID CARD (FROM TEXAS) WITH HIS NAME AND PICTURE ON IT. JAIRO INITIALLY TOLD ME A RELATIVE WAS DRIVING BUT LATER ADMITTED HE WAS THE DRIVER AND ONLY PERSON IN THE VEHICLE. JAIRO EXPLAINED THE INCIDENT OCCURRED AROUND 1930 HOURS ON AUGUST 20, 2022. JAIRO SAID

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	ME		ROUTE ID		COUNTY	CIT	Y
01089974	04-CSAH	0028	1.63	7	FOREST	PRAIRI	E RD	0400006594	850028-I	40-Le Sueur	Le	Sueur
INTERSECT WITH # VI			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	03/25/23	04:45	Sat	44.487691	-93.873092	2 430577.1	4926411.7	NOT APPLICABLE
BASIC TYPE	BASIC TYPE CRASH SEVERITY			FIRST	FIRST HARMFUL					LIGHT CONDITION WEATHER PRIF		
Single Vehicle	Other	N - Prop	N - Prop Damage Only							Dark (No Str	Lights)	Clear

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport **Unit Type** Vehicle Type Passenger Car **Direction of Travel** Northbound Maneuver Moving Forward Age/Sex 33 M **Physical Cond** Unknown **Contributing Factor 1** No Clear Contributing Action


OFFICER SKETCH NARRATIVE DRIVER 1 WAS DRIVING NORTHBOUND ON FOREST PRAIRIE ROAD AT THE POST SPEED LIMIT, APPROXIMATELY 1/4TH OF A MILE SOUTH OF THE CAMBRIA FACTORY. A DEER CAME ACROSS THE ROADWAY AND DRIVER 1 STRUCK IT, SUSTAINING DAMAGE TO THE BUMPER AND UNDERSIDE OF THEIR VEHICLE. No Diagram. Vehicles moved after collision, past-action report.



Crash Detail Report - Short Form CSAH 28 Segment 5 Year

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY		CITY	
00915018	915018 04-CSAH 0028 2.222			2	FOREST	PRAIRI	E RD	0400006594	850028-I	40-Le Sueur		Le Sueur	
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE
	1		1	0	06/28/21	14:30	Mon	44.495075	-93.86746	9 431033.0	492722	27.2	NOT APPLICABLE
BASIC TYPE CRASH SEVERITY			,	FIRST HARMFUL					LIGHT COND	TION	١	WEATHER PRIMARY	
Single Vehicle I	Single Vehicle Run Off Road N - Prop Dama			e Only	Overturn/Rollover					Daylight		F	Rain

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Medium / Heavy Trucks (More			
Direction of Travel	Southbound			
Maneuver	Turning Right			
Age/Sex	26 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Improper Turn/Merge			



NARRATIVE

I, OFFICER DANIEL REICH, RESPONDED TO A FED EX SEMI AND TRAILER WHICH WAS ROLLED ONTO ITS SIDE. I LOCATED THE SOUTH FACING SOUTH JUST SOUTH OF TECHNIPAC INC ON FOREST PRAIRIE ROAD IN LE SUEUR. THE SEMI WAS IN THE WEST DITCH. I SPOKE TO THE DRIVER, JACOB WILLIAM KAROW. JACOB SAID HE HAD JUST MADE A DELIVER AT TECHNIPAC AND WAS LEAVING THE PARKING LOT AND TURNED SOUTH (RIGHT)ONTO FOREST PRAIRIE RD. JACOB SAID HE THEN REACH UP WITH ONE OF HIS HANDS TO WIPE RAIN WATER OUT OF HIS FACE/HAIR. JACOB THEN FELT HIS TRAILER TIRES SLIDE INTO THE DITCH. JACOB SAID HE ATTEMPTED TO CONTINUE AND DRIVE SOUTH AND HOPED IT WOULD STRAIGHTEN HIS TRAILER AND GET IT BACK ONTO THE PAVEMENT. THIS RESULTED IN THE SEMI TRACTOR AND TRAILER TO ROLLOVER ONTO THE PASSENGER SIDE INTO THE DITCH. THE DITCH WAS APPROXIMATELY 8 FEET DEEP IN THIS AREA. THERE WAS VERY LITTLE SHOULDER OF THE ROADWAY IN

Selection Filter:					
WORK AREA: County('6	659485') - FILTER: Year('20)19','2020','2021','2022	2','2023') - SPATIAL FIL	TER APPLIED	
Analyst:	Notes:				
Bryan Nemeth					



Crash Detail Report - Short Form Doppy Ln and CSAH 22

		_			1			T -				
INCIDENT ID	ROUTE SYS	ROUTE NUM	ROUTE NUM MEASURE			AME.		ROUTE ID	ROUTE ID CO		CI	TY
00677668	677668 22-RAMP 4400 0.038			RAMP40	0		2200006594854400-1 40		40-Le Sueur		Sueur	
INTERSECT WIT	Н		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	01/20/19	10:11	Sun	44.482827	-93.89507	2 428823.4	4925890.	4 NOT APPLICABLE
BASIC TYPE CRASH SEVERITY				,	FIRST	HARMFU	JL			LIGHT COND	TION	WEATHER PRIMARY
Single Vehicle	Single Vehicle Run Off Road N - Prop Damage Only			e Onlv	Utility	Pole/Lic	ht Sur	port		Daylight		Clear

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Medium / Heavy Trucks (More			
Direction of Travel	Southbound			
Maneuver	Negotiating a Curve			
Age/Sex	62 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Improper Turn/Merge			

OFFICER SKETCH



NARRATIVE

UNIT 1 IS A AN OVERSIZE LOAD. IT WAS NEGOTIATING A TIGHT CLOVER LEAF STYLE ON RAMP FROM MNTH 112 TO US HWY 169 SB. UNIT 1 WAS FOLLOWING PERMIT DIRECTIONS. ROADS WERE SLIPPERY AND AS UNIT 1 WAS GOING AROUND CURVE TRAILER STARTED SLIDING OFF ROADWAY. UNIT 1 TRAILER COLLIDED WITH CABLE BARRIER END POST, BREAKING IT. IT CONTINUED SLIDING AND COLLIDED WITH A LIGHT POLE KNOCKING IT OVER. UNIT 1 HAD TO BE PULLED OUT OF SHOULDER/ROADSIDE BY TOW/RECOVERY UNIT.

Selection Filter:				
WORK AREA: County('6	59485') - FILTER: Year('2019','2	2020','2021','2022','2023') - SPATIA	L FILTER APPLIED	
Analyst:	Notes:			
Bryan Nemeth				



Crash Detail Report - Short Form TH 169 and Doppy Ln

INCIDENT ID	IDENT ID ROUTE SYS ROUTE NUM MEASURE			SURE	ROUTE NA	ME		ROUTE ID	ROUTE ID CO		C	CITY	
00706550	706550 02-USTH 0169 79.464				USTH 16	9		020000000000169-I 40		40-Le Sueur		NOT IN A CITY	
INTERSECT WIT	# VEH	# KILL	DATE	DATE TIME DAY		LAT	LONG	UTM X	UTM Y	٧	VORK ZONE TYPE		
			2	0	04/17/19	20:07	Wed	44.490972	-93.87507	3 430423.5	4926777	7.8 N	NOT APPLICABLE
BASIC TYPE CRASH SEVERIT				,	FIRST	HARMFU	JL.				TION	W	EATHER PRIMARY
Angle	Angle A - Serious Injury			V	Motor	Vehicle	In Trai	sport		Sunset		CI	ear

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1

Motor Vehicle in Transport
Passenger Car
Westbound
Moving Forward
75 M
Apparently Normal
Failure to Yield Right-of-Way

Unit 2
Motor Vehicle in Transport
Passenger Car
Southbound
Moving Forward
21 F

No Clear Contributing Action

Apparently Normal

Unit 4

Unit 4

OFFICER SKETCH

Not To Scale

DOPPY LN

TRUCK STOP

NARRATIVE

VEH 2 SB 169 RL- VEH 1- CHRYSLER DRIVEN BY JOHN SCHULTZ WAS CROSSING SB 169 ONTO DOPPY LN AND FAILED TO YIELD. VEH 2 FRONT END STRUCK VEH 1 PASS SIDE. BOTH VEHICLES TOWED BY VON ESSENS

Unit 3

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	IAME		ROUTE ID	(COUNTY	CIT	Υ
01123779	02-USTH	0169	79.47	72	USTH 16	69		02000000000	000169-D 4	10-Le Sueur	NC	T IN A CITY
INTERSECT WIT	Ĥ		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
				0	08/03/23	13:10	Thu	44.491150	-93.875308	430405.0	4926797.8	NOT APPLICABLE
BASIC TYPE	BASIC TYPE CRASH SEVERITY				FIRST HARMFUL					LIGHT CONDI	TION	WEATHER PRIMARY
Rear End	Rear End N - Prop Damage Only				Moto	Motor Vehicle In Transport						Clear


Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1
Motor Vehicle in Transport
Passenger Car
Southbound
Entering Traffic Lane
79 F
Apparently Normal

Improper Turn/Merge

Unit 2
Motor Vehicle in Transport
Passenger Car
Southbound
Moving Forward
27 M
Apparently Normal
No Clear Contributing Action

Unit 3



NARRATIVE

DRIVER TWO WAS DRIVING VEHICLE TWO SOUTHBOUND ON HIGHWAY 169 JUST NORTH OF DOPPY LANE NEAR LE SUEUR MN. DRIVER TWO STATED THEY WERE IN THE "SLOW LANE" FOLLOWING THE SPEED LIMIT. DRIVER ONE WAS DRIVING VEHICLE ONE. THEY WERE STOPPED AT THE REST AREA WHICH WAS LOCATED NEAR THE INTERSECTION OF HIGHWAY 169 AND DOPPY LANE. DRIVER ONE PULLED OUT OF THE REST AREA PARKING LOT AND CROSSED OVER THE NORTHBOUND TRAFFIC LANE. DRIVER STATED THEY SLAMMED ON THE GAS TO GET UP TO SPEED. DRIVER ONE MENTIONED THEY PULLED INTO THE "SLOW LANE" AND WAS STRUCK BY ANOTHER VEHICLE. DRIVER ONE STATED THEY DID NOT SEE ANY VEHICLES WHEN THEY ENTERED THE INTERSECTION. VEHICLE ONE SUFFERED MODERATE DAMAGE TO THE REAR. VEHICLE TWO SUFFERED MAJOR DAMAGE TO THE FRONT END, HOWEVER BOTH VEHICLES WERE OPERABLE ACCORDING TO BOTH DRIVERS. NO INJURIES WERE




Crash Detail Report - Short Form TH 169 and Doppy Ln

Selection Filter:					
WORK AREA: County	('659485') - FILTER: Year('2019','2020','2021','2022','2	2023') - SPATIAL FILTER APP	LIED	
Analyst:	Notes:				
Bryan Nemeth					



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID	ROUTE ID CO		С	ITY
01058592 02-USTH 0169 80.206				06	USTH 16	69		0200000000	000169-D	40-Le Sueur	N	IOT IN A CITY
INTERSECT WITH	# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE		
				0	11/11/22	15:39	Fri	44.499656	-93.86637	1 431125.6	4927735	5.0 NOT APPLICABLE
BASIC TYPE CRASH SEVERITY				,	FIRS1	HARMFU	JL			LIGHT CONDI	TION	WEATHER PRIMARY
Single Vehicle F	Single Vehicle Run Off Road N - Prop Damag			e Only	Cable Median Barrier			r		Daylight		Cloudy

Unit 1 Unit 2 Unit 3 **Unit Type** Motor Vehicle in Transport Vehicle Type Other Light Trucks (10,000lbs **Direction of Travel** Northbound Maneuver Making a U Turn Age/Sex 38 M **Physical Cond Apparently Normal Contributing Factor 1** Improper Turn/Merge



NARRATIVE

DRIVER WAS NORTHBOUND ON HWY 169 AND MADE A U TURN IN A CROSSOVER. WHEN THEY MADE THE U TURN THEY RAN OVER THE CABLE TENSIONER.

Unit 4

Unit 4

INCIDENT ID	NT ID ROUTE SYS ROUTE NUM MEASURE				ROUTE N	AME		ROUTE ID	ROUTE ID CO		CIT	1	
00763970	0763970 02-USTH 0169 80.219				USTH 16	89		0200000000	000169-I	I0-Le Sueur NC		OT IN A CITY	
INTERSECT WIT		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE		
					11/15/19	16:41	Fri	44.499711	-93.86590	1 431163.1	4927740.8	NOT APPLICABLE	
BASIC TYPE	BASIC TYPE CRASH SEVERITY					HARMFU	JL			LIGHT COND	TION	WEATHER PRIMARY	
Rear End	Rear End C - Possible Injury				Moto	Motor Vehicle In Transport				Daylight		Clear	

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1
Motor Vehicle in Transport
Pickup
Northbound
Moving Forward
27 M
Apparently Normal

Following Too Closely

Unit 2
Motor Vehicle in Transport
Passenger Car
Northbound
Moving Forward

19 F Apparently Normal No Clear Contributing Action Unit 3
Motor Vehicle in Transport
Medium / Heavy Trucks (More
Northbound
Slowing
31 M
Apparently Normal

No Clear Contributing Action

OFFICER SKETCH



NARRATIVE

UNIT 3 WAS IN THE LEFT TURN LANE ON US HWY 169 WAITING TO TURN LEFT AND GO SOUTHBOUND ONTO US HWY 169. UNIT 2 WAS NORTHBOUND ON US HWY 169 IN THE LEFT LANE AND UNIT 1 WAS DIRECTLY BEHIND UNIT 2 IN THE LEFT LANE. TWO VEHICLES IN FRONT OF UNIT 2 SLOWED DOWN, CAUSING UNIT 2 TO SLOW DOWN AND HIT HER BRAKES. UNIT 1 WAS FOLLOWING TO CLOSE AND COULD NOT STOP IN TIME AND REAR ENDED UNIT 2. UNIT 1 PUSHED UNIT 2 INTO THE LEFT TURN LANE, CAUSING UNIT 2 TO REAR END UNIT 3. UNIT 1 CITED FOR DUTY TO DRIVE WITH DUE CARE.



INCIDENT ID	ROUTE SYS	ROUTE NUM	I MEASURE ROUTE NAME				ROUTE ID	14	OUNTY CIT		TV		
									INOUTE ID			0111	
00849673	349673 02-USTH 0169 80.223				USTH 16	9		0200000000	000169-I	40-Le Sueur		NOT IN A CITY	
INTERSECT WIT		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE		
				0	10/15/20	19:26	Thu	44.499766	-93.865843	431167.7	4927746.9	NOT APPLICABLE	
BASIC TYPE CRASH SEVER				Y FIRST HARMFUL					LIGHT CONDI	TION	WEATHER PRIMARY		
Rear End N - Prop Dama				e Onlv	Motor	Vehicle	In Trai	nsport		Dark (Str Lig	hts On)	Clear	

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport Motor Vehicle in Transport Passenger Car Farm Vehicle (Tractor, Combi Northbound Northbound Moving Forward Moving Forward 71 M 24 M Asleep or Fatigued **Apparently Normal** Unknown No Clear Contributing Action

OFFICER SKETCH




NARRATIVE

VEHICLE 2 WAS NORTHBOUND ON US 169 ON SHOULDER AND PULLING AN AUGER. VEHICLE 1 WAS NORTHBOUND ON US 169 IN RIGHT LANE. VEHICLE 1 STRUCK THE AUGER THAT WAS BEING PULLED BY VEHICLE 2. DRIVER OF VEHICLE 1 STATED HE MAY HAVE FALLEN ASLEEP. VEHICLE 2 WAS PARTIALLY IN LANE OF TRAFFIC WITH INADEQUATE LIGHTING TO THE REAR.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	AME		ROUTE ID		COUNTY	CIT	Υ
01123573	02-USTH	0169	80.25	56	USTH 16	9		0200000000	000169-D	40-Le Sueur	NO	T IN A CITY
INTERSECT WIT	Ĥ		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
FOREST PRA	IRIE ROAD		2	0	08/02/23	16:00	Wed	44.500235	-93.86576	2 431174.7	4927798.9	NOT APPLICABLE
BASIC TYPE		CRASH SI	VERITY	,	FIRST	HARMFU	JL.			LIGHT COND	ITION	WEATHER PRIMARY
Rear End		N - Prop	Damag	e Only	Motor	Vehicle	In Trai	nsport		Daylight		Clear

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport Hit-And-Run Vehicle **Unit Type** Vehicle Type Pickup **Direction of Travel** Southbound Southbound Maneuver Moving Forward Moving Forward Age/Sex **Physical Cond Apparently Normal Contributing Factor 1** No Clear Contributing Action




NARRATIVE

VEHICLE 1 WAS TRAVELING SOUTHBOUND ON HIGHWAY 169 IN THE TURN LANE TO TURN EAST ON FORREST PRAIRIE ROAD. VEHICLE #2 (DESCRIBED AS A BLUE MINI COOPER) WAS TRAVELING SOUTHBOUND ON HIGHWAY 169 AND ATTEMPTED TO PASS A VEHICLE IN THE LEFT LANE BY USING THE TURN LANE. VEHICLE #2 STRUCK THE PASSENGER SIDE REAR OF VEHICLE #1 CAUSING DAMAGE TO THE REAR AND PASSENGER SIDE OF VEHICLE #1. VEHICLE #2 WAS REPORTED TO HAVE DAMAGE TO THE FRONT AN DRIVERS SIDE OF THE VEHICLE. VEHICLE #2 FLED THE SCENE WITHOUT PROVIDING INFORMATION. PHOTOS OF VEHICLE #1 WERE TAKEN.



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY	CIT	ſΥ
00847010	02-USTH	0169	80.2	58	USTH 16	5 9		0200000000	000169-D	40-Le Sueur	NC	OT IN A CITY
INTERSECT WI	ГН		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	10/18/20	06:15	Sun	44.500248	-93.86574	8 431175.8	4927800.3	NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	,	FIRS	T HARMFU	JL	-		LIGHT COND	ITION	WEATHER PRIMARY
Single Vehicle	Run Off Road	N - Prop	Damag	e Onlv	Guar	drail (Fac	ce)			Dark (Str Lic	ahts On)	Clear

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	19 M			
Physical Cond	Has Been Drinking Alcohol			
Contributing Factor 1	Other Contributing Action			



Unit 1

NARRATIVE

DRIVER WAS HEADED SOUTHBOUND ON 169 NEAR MM 81. THE DRIVER HIT INTO THE GUARD RAIL CAUSING MODERATE, TO HEAVY, DAMAGE ON THE DRIVER'S SIDE. THE IMPACT WAS GREAT ENOUGH TO CAUSE THE FRONT DRIVER'S SIDE TIRE TO BE REMOVED. THE DRIVER BLEW A PBT AT THE SCENE OF .09. THE DRIVER BLEW A .078 (.07) ON THE DMT. VEHICLE WAS TOWED DUE TO DAMAGE.

INCIDENT ID	NCIDENT ID ROUTE SYS ROUTE NUM MEA			SURE	ROUTE NA	AME		ROUTE ID		COUNTY	CIT	ГҮ
00901340	00901340 02-USTH 0169 80.284				USTH 16	9		0200000000	000169-D	40-Le Sueur	NC	OT IN A CITY
INTERSECT WIT	H		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	04/18/21	11:38	Sun	44.500553	-93.86542	3 431202.0	4927833.9	NOT APPLICABLE
BASIC TYPE		CRASH SI	EVERITY	,	FIRST	HARMFU	JL		-	LIGHT COND	ITION	WEATHER PRIMARY
Single Vehicle	Single Vehicle Run Off Road C - Possibl			njury Cable Median Barrier			r Dayl		Daylight		Clear	

Unit 2

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Motor Vehicle in Transport
Sport Utility Vehicle
Southbound
Moving Forward
41 F
Apparently Normal
Ran Off Road

NARRATIVE

VEHICLE 31 WAS SOUTHBOUND ON USTH 169. DRIVE STATED SHE FELL ASLEEP. VEHICLE #1 DRIFTED TO THE LEFT OFF THE ROAD ANS COLLIDED WITH CABLE MEDIAN BARRIER BEFORE COMING TO A STOP.

Unit 3

OFFICER SKETCH




Unit 4



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	AME		ROUTE ID		COUNTY	CIT	ГҮ
00680492	02-USTH	0169	80.29	90	USTH 16	9		0200000000	000169-D	40-Le Sueur	NO	OT IN A CITY
INTERSECT WIT	TH		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	01/28/19	05:05	Mon	44.500620	-93.86535	1 431207.8	4927841.4	4 NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	,	FIRST	HARMFU	JL .	-	-	LIGHT COND	ITION	WEATHER PRIMARY
Single Vehicle	Run Off Road	N - Prop	Damag	e Onlv	Guard	drail (Fac	ce)			Dark (Str Lic	ahts Off)	Snow

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	38 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	No Clear Contributing Action			
Contributing Factor 1	No Clear Contributing Action			



NARRATIVE

DRIVER OF UNIT 1 WAS DRIVING WHEN A SEMI PASSED CAUSING A COMPLETE WHITE OUT. DRIVER OF UNIT 1 DROVE INTO THE CENTER BARRIER CAUSING HEAVY DAMAGE TO DRIVER SIDE, ON MULTIPLE LOCATIONS.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY		CITY	
00865976	02-USTH	0169	80.29	98	USTH 16	89		0200000000	000169-I	40-Le Sueur		TOM	IN A CITY
INTERSECT WIT	Н		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE
			2	0	11/30/20	18:39	Mon	44.500622	-93.86493	7 431240.7	492784	1.2	NOT APPLICABLE
BASIC TYPE		CRASH SI	EVERITY	,	FIRST	HARMFU	IL			LIGHT CON	DITION	,	WEATHER PRIMARY
Rear End		N - Prop	Damag	e Only	Moto	r Vehicle	In Trai	nsport		Dark (Str L	ights On)	- (Clear

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1

Motor Vehicle in Transport
Medium / Heavy Trucks (More
Northbound
Moving Forward
34 M
Apparently Normal

No Clear Contributing Action

Unit 2
Hit-And-Run Vehicle
Passenger Car
Northbound
Moving Forward
39 F
Has Been Drinking Alcohol
Operated Motor Vehicle: Care

NARRATIVE

OFFICER SKETCH



VEHICLE 1 TURNED NORTHBOUND ONTO US 169 STATED NO ONE WAS COMING IN RIGHT LANE. DRIVER OF VEHICLE 1 STATED HE WAS ACCELERATING IN RIGHT LANE. VEHICLE 2 ALSO NORTHBOUND ON US 169. VEHICLE 2 CRASHED INTO BACK OF VEHICLE 1. BOTH VEHICLES PULLED OVER TO RIGHT. VEHICLE 2 CRASHED INTO VEHICLE 1 AGAIN WHILE PULLING OVER. DRIVER OF VEHICLE 1 GOT OUT TO ASSESS DAMAGE. VEHICLE 2'S PLATE WAS LEFT AT THE SCENE AND LEFT WITH A FLAT TIRE AND A FLUID TRAIL. VEHICLE 2 STOPPED ABOUT 6 MILES AHEAD AND REPORTED THE CRASH. DRIVER OF VEHICLE 2 WAS ARRESTED FOR DWI.


Unit 3

Unit 4



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	AME		ROUTE ID		COUNT	Υ		CITY	
00931856	04-CSAH	0028	2.57	1	FOREST	PRAIRI	E RD	0400006594	850028-I	40-Le S	Sueur		NOT	'IN A CITY
INTERSECT WIT	H		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTN	M X	UTM Y		WORK ZONE TYPE
USTH 169			1	0	08/02/21	16:34	Mon	44.499773	-93.86559	0 431	1187.8	492774	7.4	NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	,	FIRST	HARMFU	JL	•	•	LIGH	IT CONDIT	ION	١	WEATHER PRIMARY
Single Vehicle I	Run Off Road	N - Prop	Damag	e Only	Road	way Sigr	n or Sid	n Structure		Day	/light		(Clear

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Passenger Car			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	25 M			
Physical Cond	Has Been Drinking Alcohol			
Contributing Factor 1	Driver Speeding			




NARRATIVE

WITNESS REPORTED SUSPECT VEHICLE WAS TRAVELING AT HIGH RATE OF SPEED WHEN TRAVELING NORTHBOUND ON FOREST PRAIRIE ROAD. VEHICLE WAS APPROACHING ON RAMP FOR NORTHBOUND HWY 169, IT WAS TRAVELING TOO FAST TO NAVIGATE THE TURN, WENT OFF THE ROADWAY AND STRUCK A MDOT SIGN. SUSPECT VEHICLE CONTINUED TO DRIVE NORTHBOUND ON HWY 169 UNTIL COMING TO A STOP AT BRAVO LANE DUE TO DISABLING DAMAGE AS A RESULT OF THE COLLISION. DRIVER WAS ARRESTED FOR DWI.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	URE	ROUTE N	AME		ROUTE ID		COUNTY	CIT	Υ
00901161	04-CSAH	0028	2.580)	FOREST	PRAIRII	E RD	0400006594	850028-I	40-Le Sueur	NC	T IN A CITY
INTERSECT WIT	H		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
USTH 169			2	0	04/17/21	07:35	Sat	44.499849	-93.86572	6 431177.1	4927756.0	NOT APPLICABLE
BASIC TYPE		CRASH SI	VERITY		FIRST	HARMFU	IL			LIGHT COND	ITION	WEATHER PRIMARY
Angle		N - Prop	Damag	e Only	Moto	r Vehicle	In Trai	nsport		Daylight		Clear

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport Motor Vehicle in Transport **Unit Type** Vehicle Type Pickup Passenger Car **Direction of Travel** Eastbound Northbound Maneuver **Turning Left** Moving Forward Age/Sex 48 M **Physical Cond Apparently Normal Apparently Normal Contributing Factor 1** Failure to Yield Right-of-Way No Clear Contributing Action




NARRATIVE

VEHICLE 1 WAS TURNING LEFT OFF OF HWY 169 SOUTHBOUND TO GO EASTBOUND ON FOREST PRAIRIE ROAD. VEHICLE 2 WAS TRAVELING NORTHBOUND ON HWY 169 PASSING FOREST PRAIRIE ROAD. VEHICLE 1 WAS STRUCK BY VEHICLE 2 WHILE CROSSING NORTHBOUND HWY 169 TO GET TO FOREST PRAIRIE ROAD. DRIVER 1 STATED THAT HE DID NOT SEE VEHICLE 2 UNTIL HE WAS MOST OF THE WAY ACROSS HWY 169 AND THEY COLLIDED. DRIVER 2 STATED THAT VEHICLE 2 PULLED OUT TO CROSS HWY 169 IN FRONT OF HIM AND HE DID NOT HAVE TIME TO STOP BEFORE THEY COLLIDED. BOTH DRIVERS AND PASSENGERS DENIED MEDICAL ATTENTION. BOTH VEHICLES WERE TOWED DUE TO DAMAGE. PHOTOS WERE TAKEN AT THE SCENE. DRIVER 1 WAS ISSUED A CITATION FOR FAILING TO YIELD.



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COL	JNTY		CITY	
00706218	22-RAMP	4998	0.011	l	RAMP99	8		2200006594	854998-I	40-l	Le Sueur		NOT	IN A CITY
INTERSECT WIT	Н		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG		UTM X	UTM Y		WORK ZONE TYPE
			1	0	02/08/19	08:09	Fri	44.499786	-93.86593	1	431160.8	492774	19.2	NOT APPLICABLE
BASIC TYPE		CRASH S	EVERITY	,	FIRST	HARMFU	JL			Ĺ	LIGHT CONDI	TION	1	WEATHER PRIMARY
Single Vehicle	Run Off Road	N - Prop	Damag	e Only	Cable	Median	Barrie	r			Daylight		I	Rain

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Passenger Car			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	21 F			
Physical Cond	Apparently Normal			
Contributing Factor 1	Failed to Keep in Proper Lane			



NARRATIVE

TRAVELING ON THE LEFT LANE- D1 STATED SHE HIT A PATCH OF ICE, LOST CONTROL, REAR OF CAR HIT MEDIAN BARRIER CABLE, LEFT SIDE- CAR ENDED ON THE RIGHT SIDE DITCH. FRONT END ALSO HIT THE CABLE BARRIER AS IT ROTATED. HIT GUARD CABLES LEFT SIDE 169 SB NO INJURIES REPORTED ROADS WERE ICY THROUGHOUT THE HIGHWAY.

Selection Filter:

WORK AREA: County('659485')	- FILTER: Year('2019','2020','2021','2022','2023') - SPATIAL FILTER APPLIED
Analyst:	Notes:
Bryan Nemeth	



Crash Detail Report - Short Form TH 169 and Henderson Station

INCIDENT ID ROUTE SYS ROUTE NUM				MEAS	SURE	ROUTE NA	ROUTE NAME			ROUTE ID CO		COUNTY		CITY	
	01001065	08-TWNS	0013	1.33	1.335 HENDERSON STATION 08			0800006594850013-I 40-Le Sueur		r	NOT IN A CITY				
	INTERSECT WIT		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE		
			1	0	01/22/22	09:42	Sat	44.507780	-93.85794	9 431804	6 49286	30.4	NOT APPLICABLE		
	BASIC TYPE		,	FIRST HARMFUL					LIGHT CONDITION			WEATHER PRIMARY			
	Single Vehicle	Run Off Road	N - Prop	Damag	e Only	Cable	Median	Barrie	r		Daylight			Clear	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	21 F			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			

OFFICER SKETCH





NARRATIVE

VEHICLE WAS IN THE RIGHT LANE OF NORTH BOUND HWY 169 WHEN THE VEHICLE LOST CONTROL. THE VEHICLE WENT IN TO THE CENTER MEDIAN AND HIT A ONE WAY/YIELD SIGN.

INCIDENT ID ROUTE SYS ROUTE NUM			MEAS	SURE	ROUTE N	OUTE NAME		ROUTE ID CO		COUNTY		CITY	
01004196 08-TWNS 0013				.339 HENDERSON STATION 0			0800006594850013-I 40-Le Suer		40-Le Sueur	NO	T IN A CITY		
INTERSECT WIT		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE		
			1	0	01/22/22	09:55	Sat	44.507819	-93.85800	3 431800.4	4928634.8	NOT APPLICABLE	
BASIC TYPE CRASH SEVERITY					FIRST	HARMFU	IL			LIGHT COND	ITION	WEATHER PRIMARY	
Single Vehicle	Run Off Road	N - Prop	Damag	e Only	Road	way Sigr	or Sig	n Structure		Daylight		Clear	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	40 F			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			

OFFICER SKETCH



NARRATIVE

VEHICLE WAS IN THE RIGHT LANE OF NORTH BOUND HWY 169 WHEN THE VEHICLE LOST CONTROL. THE VEHICLE ENTERED THE CENTER MEDIAN HITTING THE CROSSOVER, CAUSING IT TO ROLL. THE VEHICLE ROLLED ACROSS THE CENTER MEDIAN AND CAME TO REST NEXT TO A VEHICLE FROM A PREVIOUS CRASH.




Crash Detail Report - Short Form TH 169 and Henderson Station

INCIDENT ID ROUTE SYS ROUTE NUI				MEAS	SURE	ROUTE NA	ROUTE NAME			ROUTE ID CO		COUNTY		CITY	
	01001066	0130	0.002	0.002 HE		ENDERSON STATION		1000023956590130-I 40		40-Le Sueur			Le Sueur		
	INTERSECT WIT		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTI	M X	UTM Y		WORK ZONE TYPE	
				1	0	01/22/22	10:02	Sat	44.507894	-93.85810	7 43	1792.2	492864	3.2	NOT APPLICABLE
	BASIC TYPE		EVERITY	,	FIRST	HARMFU	IL			LIGI	HT CONDIT	TION	1	WEATHER PRIMARY	
	Single Vehicle	Run Off Road	N - Prop	Damag	e Only	Cable	Median	Barrie	r		Day	/light		(Clear

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	39 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			

OFFICER SKETCH Not To Scale



NARRATIVE
VEHICLE WAS NORTH BOUND ON HWY 169 AND LOST CONTROL. THE VEHICLE WENT INTO THE CENTER MEDIAN AND HIT THE CABLE BARRIER. DAMAGE WAS DONE TO THE CABLE BARRIER.

Selection Filter:

WORK AREA: County('659485') - FILTER: Year('2019','2020','2021','2022','2023') - SPATIAL FILTER APPLIED	

Analyst:	Notes:
Bryan Nemeth	



INCIDENT ID ROUTE SYS ROUTE NUM		MEAS	SURE	ROUTE NA	ROUTE NAME		ROUTE ID	ROUTE ID CO		CIT	Υ		
01123552 02-USTH 0169			78.195		USTH 169	USTH 169		0200000000	0200000000000169-I 40-		Le	e Sueur	
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
				0	08/02/23	11:45	Wed	44.482082	-93.89646	1 428712.1	4925808.8	NOT APPLICABLE	
BASIC TYPE	CRASH SI	VERITY	,	FIRST	HARMFU	JL		-	LIGHT COND	ITION	WEATHER PRIMARY		
Single Vehicle Ru	N - Prop	Damag	e Onlv	Guard	Irail (Fac	ce)			Daylight		Clear		

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	49 F			
Physical Cond	Apparently Normal			
Contributing Factor 1	Other Contributing Action			

OFFICER SKETCH



NARRATIVE

PICKUP TRUCK WITH TRAILER WAS TRAVELING SOUTH BOUND. ACCORDING TO THE DRIVER, THE TRAILER SEPARATED. ONCE IT SEPARATED, THE FRONT OF THE TRAILER COLLIDED WITH THE WEST SIDE GUARDRAIL. UPON MY ARRIVAL, THE PIN WAS IN FOR THE HITCH BUT THE HITCH HAD CAME OFF. THE HITCH WAS DAMAGED DUE TO THE CRASH BUT THE HOLES WERE INTACT. THE DRIVER INSISTED THAT SHE HAD CONNECTED THE TRAILER CORRECTLY AND DID NOT KNOW HOW THE UNITS SEPARATED. THE TRAILER WAS FULLY LOADED. THE TRAILER WAS TOWED AWAY DUE TO DAMAGE. THE PICKUP TRUCK (PULLING UNIT) DID NOT HAVE ANY DAMAGE.

INCIDENT ID ROUTE SYS ROUTE NUM			MEAS	EASURE ROUTE NAME F			ROUTE ID		COUNTY		CITY	
01093984 02-USTH 0169				78.234 US		STH 169		0200000000000169-I 40-		40-Le Sueur		Sueur
INTERSECT WIT	i	# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
30 F N EXIT R	AMP TO LE SU	JEUR CR 22	1	0	04/16/23	00:52	Sun	44.482205	-93.89570	0 428772.8	4925821.	.8 NOT APPLICABLE
BASIC TYPE		VERITY		FIRST	HARMFU	L			LIGHT CONDI	TION	WEATHER PRIMARY	
Single Vehicle Run Off Road N - Prop				Only	Guard	rail (Fac	e)			Dark (Str Lig	hts On)	Snow

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	28 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Ran Off Road			

OFFICER SKETCH




NARRATIVE

VEHICLE NORTHBOUND 169. DRIVER LOST CONTROL OF VEHICLE NEAR THE EXIT RAMP TO LE SUEUR COUNTY ROAD 22. VEHICLE HIT GUARD RAIL AND CAME TO FINAL REST ON NORTHBOUND SHOULDER.



INCIDENT ID	ENT ID ROUTE SYS ROUTE NUM MEASURE			ROUTE NA	ME		ROUTE ID		COUNTY		CITY	
00770397	02-USTH	0169	78.3	43	USTH 16	9		020000000000169-D 4		40-Le Sueur		Sueur
INTERSECT WITH		# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
				0	12/07/19	04:40	Sat	44.482673	-93.89387	4 428918.5	4925872.2	NOT APPLICABLE
BASIC TYPE	ASIC TYPE CRASH SEVERITY				FIRST	HARMFU	JL			LIGHT COND	TION	WEATHER PRIMARY
Single Vehicle F	single Vehicle Run Off Road N - Prop Damage Only				Utility	Utility Pole/Light Support					ıhts On)	Clear

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Southbound			
Maneuver	Swerved or Attempt to Avoid			
Age/Sex	36 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Over Correcting / Over Steeri			



NARRATIVE

VEHICLE #1 A 2003 GMC YUKON (MN 773-WMP) DRIVEN BY ANTWAIN LEWIS 03-21-1983 WAS TRAVELING SOUTH ON HWY 169 AND ABOUT TO TAKE THE HWY 112 EXIT. THE DRIVER CLAIMED SOME DEER RAN ACROSS THE ROAD, AND HE THEN SWERVED BACK TOWARDS THE TRAFFIC LANE TO AVOID THEM. THIS CAUSED HIM TO LOOSE CONTROL AND SPIN OUT, GOING OFF ROAD AND STRIKING A MNDOT LIGHT POLE AND KNOCKING IT DOWN. THE VEHICLE WAS THEN STUCK IN A STEEP RAVINE. THE DRIVER DID NOT DISPLAY ANY INDICATORS OF IMPAIRMENT, AND PROVIDED CURRENT INSURANCE INFORMATION ON THE VEHICLE. VON ESSEN'S TOWING WAS ABLE TO WINCH HIM FROM THE RAVINE, AND THE VEHICLE WAS STILL OPERABLE. THE STATE PATROL WAS ADVISED OF THE CRASH AND DAMAGE TO PROPERTY. THEY CREATED AN EVENT AND NOTIFIED MNDOT. STATE ACCIDENT REPORT DONE ON-LINE. CLEARED.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE I	NAME		ROUTE ID	(COUNTY	CI	CITY	
00938877	02-USTH	* * * * * * * * * * * * * * * * * * * *			USTH 1	169		02000000000	000169-D	10-Le Sueur	Le	Sueur	
INTERSECT WIT	# VEH	# KILL	DATE	DATE TIME DAY		LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE			
			1	0	09/04/21	1 19:46	Sat	44.482734	-93.893497	428948.6	4925878.	6 NOT APPLICABLE	
BASIC TYPE	ASIC TYPE CRASH SEVERITY				FIRS	ST HARMFU	L			LIGHT CONDI	TION	WEATHER PRIMARY	
Single Vehicle	Single Vehicle Run Off Road N - Prop Damage Only			Roa	adway Sign	gn Structure		Daylight		Clear			

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Passenger Car			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	22 F			
Physical Cond	Has Been Drinking Alcohol			
Contributing Factor 1	Operated Vehicle: Reckless/#			

OFFICER SKETCH




NARRATIVE

VEHICLE 1 WAS SOUTHBOUND ON US 169 DRIVING ERRATICALLY, PASSING ON SHOULDER AND DRIVING AT AN ESTIMATED 90 TO 100 MPH. VEHICLE LOST CONTROL WHILE PASSING WENT OFF THE ROAD TO THE RIGHT STRUCK A SIGN AND THEN SWERVED BACK INTO THE LANES OF TRAFFIC NEARLY CAUSING ANOTHER CRASH. OTHER VEHICLES STRUCK THE SIGN THAT WAS IN THE ROADWAY DISABLING THEIR VEHICLES.




INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY		CITY	
00998710	02-USTH	0169	78.40)1	USTH 16	STH 169 02		0200000000	020000000000169-D 40			Le S	Sueur
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE
				0	01/05/22	09:47	Wed	44.482857	-93.89272	4 429010.2	492589	1.7	NOT APPLICABLE
BASIC TYPE	ASIC TYPE CRASH SEVERITY				FIRST	FIRST HARMFUL					LIGHT CONDITION		WEATHER PRIMARY
Single Vehicle F	un Off Road N - Prop Damage Only			Cable	Cable Median Barrier					Daylight		Cloudy	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Sport Utility Vehicle			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	33 F			
Physical Cond	Apparently Normal			
Contributing Factor 1	Failed to Keep in Proper Lane			



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE NA	ME		ROUTE ID		COUNTY		CITY	
01055643	02-USTH	0169	78.42	24				020000000000169-I 40-		40-Le Sueur		Le Sueur	
INTERSECT WITH # VEH # KILI			# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y		WORK ZONE TYPE	
			1	0	11/03/22	11/03/22 05:50 Thu		44.482780	-93.89194	6 429072.0	492588	32.4	NOT APPLICABLE
BASIC TYPE	BASIC TYPE CRASH SEVERITY			,	FIRST HARMFUL					LIGHT COND	ITION	1	WEATHER PRIMARY
Single Vehicle I	Single Vehicle Run Off Road N - Prop Damage Only			e Only	Guardrail (End)					Dark (No St	Lights)	(Clear

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport **Unit Type** Vehicle Type Sport Utility Vehicle **Direction of Travel** Northbound Maneuver Moving Forward Age/Sex **Physical Cond Apparently Normal Contributing Factor 1** Swerved or Avoided Due to V



NARRATIVE

DRIVER ONE WAS DRIVING VEHICLE ONE NORTHBOUND ON HWY 169
NEAR COUNTY ROAD 22. DRIVER ONE OBSERVED A DEER IN THE
ROADWAY AND SWERVED TO THE RIGHT TO MISS IT. DRIVER ONE'S
VEHICLE COLLIDED WITH A GUARD RAIL THAT WAS ON THE EAST SIDE
OF THE ROAD. VEHICLE ONE WAS STUCK ON THE GUARD RAIL AND
REQUIRED A TOW TRUCK TO COME AND PULL IT FREE. THE TOW
ARRIVED ON SCENE AND PULLED THE VEHICLE AWAY FROM THE RAIL,
THE VEHICLE WAS DRIVABLE AND WAS ABLE TO LEAVE THE SCENE
UNDER IT'S OWN POWER. INSURANCE WAS FOUND TO BE VALID
THROUGH NORTH STAR 000221041. STATE ACCIDENT REPORT
COMPLETED ONLINE. NO DAMAGE TO THE GUARD RAILS WAS
OBSERVED. BWC AVAILABLE END OF REPORT



INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SIIDE	ROUTE NA	ME		ROUTE ID		COUNTY	CIT	CITY	
INCIDENT ID	COULT 313	NOUTE NUM	WILAS	OKE	KOUTE NA	VIAIT.		KOUTEID		COUNTI	CII	OILI	
00677332)2-USTH (0169 78.431			USTH 169			020000000000169-I 40-		40-Le Sueur		Sueur	
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
			1	0	01/18/19	16:08	Fri	44.482800	-93.89181	0 429082.8	4925884.5	NOT APPLICABLE	
BASIC TYPE	BASIC TYPE CRASH SEVERITY				FIRST	FIRST HARMFUL				LIGHT COND	TION	WEATHER PRIMARY	
Single Vehicle R	Single Vehicle Run Off Road N - Prop Damage Only				Stand	Standing Tree/Shrubbery						Snow	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Pickup			
Direction of Travel	Northbound			
Maneuver	Moving Forward			
Age/Sex	22 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Swerved or Avoided Due to V			

OFFICER SKETCH






NARRATIVE

THE VEHICLE WAS NORTHBOUND ON USTH 169. THE DRIVER WAS UNSURE IF ANOTHER VEHICLE BUMPED HIM OR IF HE HIT AN ICE/SNOW MIXTURE THAT CAUSED HIM TO SLIDE OFF THE ROAD. THE DRIVER STATED THAT THERE WAS ANOTHER VEHICLE CLOSE TO HIM IN THE LEFT LANE. THE VEHICLE RAN OFF THE ROAD TO THE RIGHT AND THEN WENT DOWN A STEEP GRADE SHOULDER AND HIT MULTIPLE SMALL PINE TREES. THE VEHICLE WAS PULLED OUT OF THE VEGETATION BY VON ESSEN'S TOWING. NO INJURIES WERE REPORTED.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY	CIT	Υ
01059863	02-USTH				USTH 16	9		0200000000	000169-I	40-Le Sueur Le		Sueur
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	11/20/22	05:30	Sun	44.482879	-93.89127	4 429125.5	4925892.8	NOT APPLICABLE
BASIC TYPE	ASIC TYPE CRASH SEVERITY				FIRST	FIRST HARMFUL			-	LIGHT COND	TION	WEATHER PRIMARY
Single Vehicle	ngle Vehicle Other C - Possible Injury			Deer	Deer				Dark (No Str	Lights)	Clear	

Unit 1 Unit 2 Unit 3 Unit 4 Motor Vehicle in Transport **Unit Type** Vehicle Type Sport Utility Vehicle **Direction of Travel** Northbound Maneuver Moving Forward Age/Sex **Physical Cond Apparently Normal Contributing Factor 1** No Clear Contributing Action




NARRATIVE

DRIVER ONE WAS DRIVING VEHICLE ONE NORTHBOUND ON HIGHWAY 169 NEAR LE SUEUR COUNTY ROAD 22 WHEN A DEER IN THE ROADWAY RAN ACROSS THE LANE OF TRAFFIC AND COLLIDED WITH THE FRONT END OF THE VEHICLE CAUSING DISABLING DAMAGE TO THE VEHICLE. OFFICER ARRIVED ON SCENE AND CHECKED ON BOTH OCCUPANTS. THE DRIVER, RONALD, WAS NOT INJURED. HE STATED HE WAS DRIVING WHEN HE OBSERVED A DEER IN THE ROADWAY, THE DEER CROSSED OVER HIS LANE OF TRAFFIC AND IT COLLIDED WITH THE FRONT OF HIS VEHICLE. I ALSO SPOKE WITH THE FRONT SEAT PASSENGER, NANCY, WHO WAS COUGHING EXCESSIVELY. NANCY HAD ASTHMA WHICH WAS AGGRAVATED WHEN THE AIRBAGS DEPLOYED, AS SHE HAD INHALED SOME OF THE AIR BAG DUST. NANCY WAS CHECKED OUT BY AN AMBULANCE BUT WAS NOT TRANSPORTED. NANCY AND RONALD WERE BOTH BELTED DURING THE CRASH. I REMOVED A LARGE DOE FROM THE ROADWAY AND



					T = =				-				
INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	SURE	ROUTE N	AME		ROUTE ID		COUNTY	CI	CITY	
00896147	02-USTH	0169	78.48	32	USTH 16	9		020000000000169-D 40		40-Le Sueur	Le	Sueur	
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE	
			1	0	03/15/21	07:04	Mon	44.483111	-93.89113	4 429136.9	4925918.	NOT APPLICABLE	
BASIC TYPE	BASIC TYPE CRASH SEVERITY				FIRST	FIRST HARMFUL					TION	WEATHER PRIMARY	
Single Vehicle F	Single Vehicle Run Off Road N - Prop Damage Only				Road	Roadway Sign or Sign Structure					Liahts)	Snow	

	Unit 1	Unit 2	Unit 3	Unit 4
Unit Type	Motor Vehicle in Transport			
Vehicle Type	Passenger Car			
Direction of Travel	Southbound			
Maneuver	Moving Forward			
Age/Sex	18 M			
Physical Cond	Apparently Normal			
Contributing Factor 1	Ran Off Road			



NARRATIVE

UNIT 1 WAS TRAVELING SOUTHBOUND USTH 169 WHEN HIS VEHICLE STARTED TO SLIDE. DRIVER COULD NOT GAIN CONTROL OF THE VEHICLE WENT OFF THE ROADWAY TO THE RIGHT AND STUCK AN INFORMATIONAL SIGN FOR THE LE SUEUR EXIT.

INCIDENT ID	ROUTE SYS	ROUTE NUM	MEAS	URE	ROUTE	NAME		ROUTE ID		COUNTY	CI	TY
00892183	02-USTH	0169	78.491 US		USTH 1	USTH 169 02000		0200000000	0000000000169-D 40-Le Sueur		Le Sueur	
INTERSECT WITH			# VEH	# KILL	DATE	TIME	DAY	LAT	LONG	UTM X	UTM Y	WORK ZONE TYPE
			1	0	02/21/21	1 17:44	Sun	44.483139	-93.890950	429151.6	4925921.	4 NOT APPLICABLE
BASIC TYPE CRASH SEVERITY			FIRS	FIRST HARMFUL			LIGHT CONDITION		WEATHER PRIMARY			
Single Vehicle	Run Off Road	N - Prop Damage Only			Cab	Cable Median Barrier			Dark (Str Lights On)		Snow	

Unit 2

Unit Type
Vehicle Type
Direction of Travel
Maneuver
Age/Sex
Physical Cond
Contributing Factor 1

Unit 1
Motor Vehicle in Transport
Sport Utility Vehicle
Southbound
Moving Forward
19 M
Apparently Normal
Operated Motor Vehicle: Care

NARRATIVE

VEHICLE WAS SOUTHBOUND ON US169. VEHICLE LOST CONTROL AND WENT INTO CEMENT BARRIER THEN WENT TO THE RIGHT HAND SIDE AND STUCK THE CABLE BARRIER TO THE RIGHT. VEHICLE WENT PAST THE CABLE BARRIER INTO THE DITCH DRIVER STATED HE WAS GOING 65 MPH. ROAD CONDITIONS WERE NOT IDEAL AND CAUTION SHOULD HAVE BEEN TAKEN. DRIVER STATED THAT HE HIT A PATCH OF "BLACK ICE." NO OTHER VEHICLES SEEMED TO BE HAVING ANY ISSUES. DRIVER ISSUED CITATION FOR DUTY TO DRIVE WITH DUE CARE

Unit 3

OFFICER SKETCH



Unit 4



Selection Filter:							
WORK AREA: County('659485') - FILTER: Year('2019','2020','2021','2022','2023') - SPATIAL FILTER APPLIED							
Analyst:	Notes:						
Bryan Nemeth							